



Movement that inspires

SVHC List

[KIA MOTORS EUROPE] NIRO EV (SG2 EV)

| Area | Parts | SVHCs present in component articles at greater than 0.1% w/w (CAS No) |
|------|--------------------------------|---|
| BODY | STRUCTURE | Melamine(108-78-1);Imidazolidine-2-thione(96-45-7);Cobalt-dinitrate(10141-05-6);Lead(7439-92-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Octamethylcyclotetrasiloxane(556-67-2);Decamethylcyclopentasiloxane(541-02-6); Cobalt(II) nitrate hexahydrate(10026-22-9);C,C'-azodi(formamide)(123-77-3) |
| | BRAKE | Melamine(108-78-1);C,C'-azodi(formamide)(123-77-3);Diboron-trioxide(1303-86-2);Lead(7439-92-1);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Disodium tetraborate, anhydrous(1330-43-4);Nonoxinol(9016-45-9);Boric acid(10043-35-3);4,4'-Isopropylidenediphenol(80-05-7); Lead-monoxide(1317-36-8);Nonylphenol(25154-52-3);Octamethylcyclotetrasiloxane(556-67-2);Decamethylcyclopentasiloxane(541-02-6);Dodecamethylcyclohexasiloxane(540-97-6) |
| | BUMPER | Lead(7439-92-1);Melamine(108-78-1);Phenol, dimethyl-, phosphate (3:1)(25155-23-1);Cobalt-dinitrate(10141-05-6);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Octamethylcyclotetrasiloxane(556-67-2);Decamethylcyclopentasiloxane(541-02-6);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);TBBA(79-94-7) |
| | GLASS GLASS MOULDING | Di-(2-ethylhexyl)phthalat(117-81-7);Lead(7439-92-1);Imidazolidine-2-thione(96-45-7);Diboron-trioxide(1303-86-2);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);2-Ethoxyethyl acetate(111-15-9);Lead-monoxide(1317-36-8) |
| | OUTSIDE LAMP OURSIDE MIRROR | C,C'-azodi(formamide)(123-77-3);Melamine(108-78-1);Lead(7439-92-1);Phenol, dimethyl-, phosphate (3:1)(25155-23-1);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);2-Ethoxyethyl acetate(111-15-9);Octamethylcyclotetrasiloxane(556-67-2);Cobalt-dinitrate(10141-05-6);Boric acid(10043-35-3);1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione(2451-62-9) |
| | WHEEL TIRE | Boric acid(10043-35-3);Lead(7439-92-1);Lead titanium zirconium oxide(12626-81-2);Octamethylcyclotetrasiloxane(556-67-2);Decamethylcyclopentasiloxane(541-02-6);Dodecamethylcyclohexasiloxane(540-97-6);1,2-Dimethoxyethane(110-71-4);1,3-Propanesultone(1120-71-4) |
| | THE OTHERS | Melamine(108-78-1);Lead(7439-92-1);Boric acid(10043-35-3);Lead-monoxide(1317-36-8);Acrylamide(79-06-1);C,C'-azodi(formamide)(123-77-3);Cobalt-dinitrate(10141-05-6);Cobalt sulphate(10124-43-3);Alkanes, C14-17, chloro(85535-85-9);1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione(2451-62-9);2-Methyl-1-(4- |

| | | |
|---------------------|--------------------------|---|
| | | methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Octamethylcyclotetrasiloxane(556-67-2);Decamethylcyclopentasiloxane(541-02-6);Decamethylcyclopentasiloxane(541-02-6);N,N-Dimethylacetamide(127-19-5);Imidazolidine-2-thione(96-45-7);2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol(25973-55-1);Diboron-trioxide(1303-86-2);Anthracene(120-12-7) |
| DOOR SUNROOF | DOOR | Lead(7439-92-1);C,C'-azodi(formamide)(123-77-3);Cobalt sulphate(10124-43-3);Cobalt-dinitrate(10141-05-6);Phenol, dimethyl-, phosphate (3:1)(25155-23-1);Tris(2-chloroethyl) phosphate(115-96-8);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);TBBA(79-94-7);N,N-Dimethylacetamide(127-19-5);Cobalt(II) nitrate hexahydrate(10026-22-9);Hexahydromethylphthalic-anhydride(25550-51-0);Lead titanium zirconium oxide(12626-81-2) |
| | HOOD | Lead(7439-92-1);Imidazolidine-2-thione(96-45-7) |
| | SUNROOF | C,C'-azodi(formamide)(123-77-3);Lead(7439-92-1);1-Methyl-2-pyrrolidone(872-50-4);N,N-Dimethylformamide(68-12-2);Cobalt(II) nitrate hexahydrate(10026-22-9);TBBA(79-94-7);Lead-monoxide(1317-36-8);Octamethylcyclotetrasiloxane(556-67-2);Decamethylcyclopentasiloxane(541-02-6) |
| | TRUNK TAIL GATE | Lead(7439-92-1);Cobalt-dinitrate(10141-05-6);Imidazolidine-2-thione(96-45-7);2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone(119313-12-1);Lead-monoxide(1317-36-8);Lead-titanium-trioxide(12060-00-3);Diboron-trioxide(1303-86-2);Octamethylcyclotetrasiloxane(556-67-2);Decamethylcyclopentasiloxane(541-02-6) |
| | THE OTHERS | Lead(7439-92-1) |
| ELECTRIC CONTROL | ELECTRIC CONTROL | Melamine(108-78-1);Lead(7439-92-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Boric acid(10043-35-3);N,N-Dimethylacetamide(127-19-5);Cobalt-dinitrate(10141-05-6);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);4-(1,1,3,3-Tetramethylbutyl)phenol(140-66-9);Lead titanium zirconium oxide(12626-81-2);Octamethylcyclotetrasiloxane(556-67-2);Decamethylcyclopentasiloxane(541-02-6);Cobalt chloride(7791-13-1);TBBA(79-94-7); Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide(75980-60-8) |
| | WIRING HARNESS | Lead(7439-92-1);Melamine(108-78-1);Tris(2-chloroethyl) phosphate(115-96-8);TBBA(79-94-7);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Lead-monoxide(1317-36-8);Tris(2-methoxyethoxy)vinylsilane(1067-53-4);Decamethylcyclopentasiloxane(541-02-6);Octamethylcyclotetrasiloxane(556-67-2);C,C'-azodi(formamide)(123-77-3);Diboron-trioxide(1303-86-2);Phenol, dimethyl-, phosphate (3:1)(25155-23-1);Cobalt-dinitrate(10141-05-6);Dioctyltin dilaurate(3648-18-8) |
| ENGINE ROOM | ENGINE TRANSMISSION | Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Lead(7439-92-1);Lead-titanium-trioxide(12060-00-3);Boric acid(10043-35-3);Dodecamethylcyclohexasiloxane(540-97-6);Cobalt-dinitrate(10141-05-6);Decamethylcyclopentasiloxane(541-02-6);1-Methyl-2-pyrrolidone(872-50-4);Cobalt-dichloride(7646-79-9);Cobalt sulphate(10124-43-3);Octamethylcyclotetrasiloxane(556-67-2);Lead titanium zirconium oxide(12626-81-2);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);2-Methylimidazole(693-98-1) |
| | HEATER & COOLING UNIT | Lead(7439-92-1);Tris(2-chloroethyl) phosphate(115-96-8);Hexahydromethylphthalic-anhydride(25550-51-0);N,N-Dimethylacetamide(127-19-5);C,C'-azodi(formamide)(123-77-3);Lead- |

| | | |
|----------|---------------------------------|--|
| | | monoxide(1317-36-8);TBBA(79-94-7);Lead-titanium-trioxide(12060-00-3);Diboron-trioxide(1303-86-2) |
| | THE OTHERS | Lead(7439-92-1);Melamine(108-78-1);Lead-monoxide(1317-36-8);Cobalt-dinitrate(10141-05-6);Diboron-trioxide(1303-86-2);Cobalt sulphate(10124-43-3);Tris(nonylphenyl)phosphite(26523-78-4);Octamethylcyclotetrasiloxane(556-67-2);4,4'-Isopropylidenediphenol(80-05-7);Lead-titanium-trioxide(12060-00-3);Decamethylcyclopentasiloxane(541-02-6);Tris(2-chloroethyl) phosphate(115-96-8);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);TBBA(79-94-7);N,N-Dimethylacetamide(127-19-5);Tris(2-methoxyethoxy)vinylsilane(1067-53-4) |
| INTERIOR | AIR BAG | |
| | CONSOLE | Lead-monoxide(1317-36-8);Lead(7439-92-1);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Octamethylcyclotetrasiloxane(556-67-2);Decamethylcyclopentasiloxane(541-02-6);TBBA(79-94-7);Tris(2-chloroethyl) phosphate(115-96-8);Cobalt-dinitrate(10141-05-6);4-Methylcyclohexyl-1,6-dicarboxylic acid anhydride(19438-60-9);Diboron-trioxide(1303-86-2);Glycols, polyethylene, mono(p-(1,1,3,3-tetramethylbutyl)phenyl) ether(9002-93-1);Lead-titanium-trioxide(12060-00-3) |
| | CRASH PAD | Lead(7439-92-1);Octamethylcyclotetrasiloxane(556-67-2);Tris(2-chloroethyl) phosphate(115-96-8);Cobalt sulphate(10124-43-3);2-Ethoxyethyl acetate(111-15-9);1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione(2451-62-9);Cyclohexane-1,2-dicarboxylic anhydride(85-42-7);TBBA(79-94-7);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Lead-monoxide(1317-36-8);Nonoxinol(9016-45-9);Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide(75980-60-8) |
| | DISPLAY | Boric acid(10043-35-3);Lead(7439-92-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Lead titanium zirconium oxide(12626-81-2);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione(2451-62-9);Tris(2-chloroethyl) phosphate(115-96-8);Hexahydromethylphthalic-anhydride(25550-51-0);TBBA(79-94-7);4,4'-Isopropylidenediphenol(80-05-7);Melamine(108-78-1);Lead-titanium-trioxide(12060-00-3);1-Methyl-2-pyrrolidone(872-50-4) |
| | HEADLINING | C,C'-azodi(formamide)(123-77-3);Lead(7439-92-1);Tris(2-chloroethyl) phosphate(115-96-8);TBBA(79-94-7);Lead-monoxide(1317-36-8) |
| | SEAT ARM REST | Lead(7439-92-1);N,N-Dimethylformamide(68-12-2);C,C'-azodi(formamide)(123-77-3);Cobalt-dinitrate(10141-05-6);N,N-Dimethylacetamide(127-19-5);Tris(2-chloroethyl) phosphate(115-96-8);Melamine(108-78-1);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Cobalt sulphate(10124-43-3);Octamethylcyclotetrasiloxane(556-67-2);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Cobalt-sulfate-heptahydrate(10026-24-1);Glycols, polyethylene, mono(p-(1,1,3,3-tetramethylbutyl)phenyl) ether(9002-93-1);Lead titanium zirconium oxide(12626-81-2);2-Ethoxyethanol(110-80-5) |
| | SEAT BELT PRETENTIONER | Cobalt-dinitrate(10141-05-6);Lead(7439-92-1);Cobalt(II) nitrate hexahydrate(10026-22-9);Cobalt-dichloride(7646-79-9);Acetic acid, cobalt(2+) salt, tetrahydrate(6147-53-1);Cobalt sulphate(10124-43-3) |
| | STEERING WHEEL GEAR SHIFT LEVER | Lead(7439-92-1);Tris(2-chloroethyl) phosphate(115-96-8);TBBA(79-94-7);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Cobalt-dinitrate(10141-05-6);Cobalt(II) nitrate hexahydrate(10026-22-9) |

| | | |
|---------------------|-------------------------------|---|
| | SWITCHES CONTROLLER | Lead(7439-92-1);Lead-monoxide(1317-36-8) |
| | THE OTHERS | Melamine(108-78-1);Lead(7439-92-1);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);C,C'-azodi(formamide)(123-77-3);N,N-Dimethylformamide(68-12-2);Cobalt-dinitrate(10141-05-6);Tris(2-chloroethyl) phosphate(115-96-8);TBBA(79-94-7);N,N-Dimethylacetamide(127-19-5);Cobalt(II) nitrate hexahydrate(10026-22-9);Octamethylcyclotetrasiloxane(556-67-2);Decamethylcyclopentasiloxane(541-02-6);Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide(75980-60-8) |
| STEERING SUSPENSION | SUSPENSION | Boric acid(10043-35-3);Lead(7439-92-1);Melamine(108-78-1);Tris(nonylphenyl)phosphite(26523-78-4);Cobalt-dinitrate(10141-05-6);2-Methylimidazole(693-98-1);Imidazolidine-2-thione(96-45-7);Diboron-trioxide(1303-86-2);4,4'-Isopropylidenediphenol(80-05-7) |
| | STEERING | Melamine(108-78-1);Lead-monoxide(1317-36-8);Lead(7439-92-1) |
| BATTERY | BATTERY & MANAGEMENT SYSTEM | Lead(7439-92-1);Melamine(108-78-1);Cobalt chloride(7791-13-1);C,C'-azodi(formamide)(123-77-3);Lead-monoxide(1317-36-8);Imidazolidine-2-thione(96-45-7);Diboron-trioxide(1303-86-2);Cobalt sulphate(10124-43-3);Tris(nonylphenyl)phosphite(26523-78-4);Octamethylcyclotetrasiloxane(556-67-2);Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide(75980-60-8) |
| | FUEL CELL & MANAGEMENT SYSTEM | |
| THE OTHERS | E-SCOOTER | |
| | CUSTOMIZING PART | |

No specific safe use information is required – follow General Safe Use Information for Articles.



Movement that inspires

SVHC List

[KIA MOTORS EUROPE] NIRO Hybrid (SG2 HEV)

| Area | Parts | SVHCs present in component articles at greater than 0.1% w/w (CAS No) |
|------|--------------------------------|---|
| BODY | STRUCTURE | Lead(7439-92-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Octamethylcyclotetrasiloxane(556-67-2);Decamethylcyclopentasiloxane(541-02-6);C,C'-azodi(formamide)(123-77-3) |
| | BRAKE | Melamine(108-78-1);C,C'-azodi(formamide)(123-77-3);Diboron-trioxide(1303-86-2);4,4'-Isopropylidenediphenol(80-05-7);Lead(7439-92-1);Lead-monoxide(1317-36-8);Lead-titanium-trioxide(12060-00-3);Octamethylcyclotetrasiloxane(556-67-2);Decamethylcyclopentasiloxane(541-02-6);Dodecamethylcyclohexasiloxane(540-97-6);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5) |
| | BUMPER | Melamine(108-78-1);Boric acid(10043-35-3);Lead(7439-92-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Octamethylcyclotetrasiloxane(556-67-2);Decamethylcyclopentasiloxane(541-02-6);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);TBBA(79-94-7) |
| | GLASS GLASS MOULDING | Lead(7439-92-1);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Lead-monoxide(1317-36-8) |
| | OUTSIDE LAMP OUTSIDE MIRROR | C,C'-azodi(formamide)(123-77-3);Melamine(108-78-1);Phenol, dimethyl-, phosphate (3:1)(25155-23-1);Lead(7439-92-1);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Cobalt-dinitrate(10141-05-6);Boric acid(10043-35-3);Cobalt(II) nitrate hexahydrate(10026-22-9) |
| | WHEEL TIRE | Lead titanium zirconium oxide(12626-81-2);Decamethylcyclopentasiloxane(541-02-6);Dodecamethylcyclohexasiloxane(540-97-6);1,2-Dimethoxyethane(110-71-4);1,3-Propanesultone(1120-71-4);Lead(7439-92-1) |
| | THE OTHERS | Melamine(108-78-1);Lead(7439-92-1);Diboron-trioxide(1303-86-2);Lead titanium zirconium oxide(12626-81-2);Octamethylcyclotetrasiloxane(556-67-2);Decamethylcyclopentasiloxane(541-02-6);C,C'-azodi(formamide)(123-77-3);Dodecamethylcyclohexasiloxane(540-97-6);Lead-monoxide(1317-36-8);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Alkanes, C14-17, chloro(85535-85-9);N,N-Dimethylacetamide(127-19-5);Imidazolidine-2-thione(96-45-7);2-(2H- |

| | | |
|---------------------|--------------------------|--|
| | | Benzotriazol-2-yl)-4,6-ditertpentylphenol(25973-55-1);Boric acid(10043-35-3);Bis(4-chlorophenyl) sulfon(80-07-9) |
| DOOR SUNROOF | DOOR | C,C'-azodi(formamide)(123-77-3);Phenol, dimethyl-, phosphate (3:1)(25155-23-1);Tris(2-chloroethyl) phosphate(115-96-8);Lead(7439-92-1);Lead-monoxide(1317-36-8);6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol(119-47-1);Lead-titanium-trioxide(12060-00-3);TBBA(79-94-7);Cobalt(II) nitrate hexahydrate(10026-22-9);Diboron-trioxide(1303-86-2);Hexahydromethylphthalic-anhydride(25550-51-0);Lead titanium zirconium oxide(12626-81-2);Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide(75980-60-8) |
| | HOOD | Imidazolidine-2-thione(96-45-7) |
| | SUNROOF | C,C'-azodi(formamide)(123-77-3);Lead(7439-92-1);Cobalt(II) nitrate hexahydrate(10026-22-9);Lead-monoxide(1317-36-8);Octamethylcyclotetrasiloxane(556-67-2);Decamethylcyclopentasiloxane(541-02-6) |
| | TRUNK TAIL GATE | Lead(7439-92-1);Lead-monoxide(1317-36-8);Lead-titanium-trioxide(12060-00-3);Diboron-trioxide(1303-86-2);Octamethylcyclotetrasiloxane(556-67-2);Decamethylcyclopentasiloxane(541-02-6) |
| | THE OTHERS | |
| ELECTRIC CONTROL | ELECTRIC CONTROL | Melamine(108-78-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Lead(7439-92-1);Lead titanium zirconium oxide(12626-81-2);Octamethylcyclotetrasiloxane(556-67-2);Decamethylcyclopentasiloxane(541-02-6);4-Methylcyclohexyl-1,6-dicarboxylic acid anhydride(19438-60-9);Cobalt chloride(7791-13-1);TBBA(79-94-7);Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide(75980-60-8) |
| | WIRING HARNESS | TBBA(79-94-7);Lead(7439-92-1);Melamine(108-78-1);C,C'-azodi(formamide)(123-77-3);Lead-monoxide(1317-36-8);Octamethylcyclotetrasiloxane(556-67-2);Decamethylcyclopentasiloxane(541-02-6);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5) |
| ENGINE ROOM | ENGINE TRANSMISSION | Melamine(108-78-1);Lead(7439-92-1);Di-(2-ethylhexyl)phthalat(117-81-7);Lead-monoxide(1317-36-8);Boric acid(10043-35-3);Octamethylcyclotetrasiloxane(556-67-2);Diboron-trioxide(1303-86-2);Butylbenzylphthalate(85-68-7);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);1-Methyl-2-pyrrolidone(872-50-4);Decamethylcyclopentasiloxane(541-02-6);Dodecamethylcyclohexasiloxane(540-97-6);TBBA(79-94-7);Bis(4-chlorophenyl) sulfon(80-07-9) |
| | HEATER & COOLING UNIT | Hexahydromethylphthalic-anhydride(25550-51-0);C,C'-azodi(formamide)(123-77-3);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Lead(7439-92-1);Tris(2-chloroethyl) phosphate(115-96-8) |
| | THE OTHERS | Diboron-trioxide(1303-86-2);Melamine(108-78-1);Lead(7439-92-1);Lead-monoxide(1317-36-8);Decamethylcyclopentasiloxane(541-02-6);Dodecamethylcyclohexasiloxane(540-97-6);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Tris(2-methoxyethoxy)vinylsilane(1067-53-4);Octamethylcyclotetrasiloxane(556-67-2) |
| INTERIOR | AIR BAG | Lead(7439-92-1);Lead titanium zirconium oxide(12626-81-2) |
| | CONSOLE | Lead(7439-92-1);Lead-monoxide(1317-36-8);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Octamethylcyclotetrasiloxane(556-67-2) |

| | | |
|---------------------|---------------------------------|---|
| | | 2);Decamethylcyclopentasiloxane(541-02-6);TBBA(79-94-7);Tris(2-chloroethyl) phosphate(115-96-8);Diboron-trioxide(1303-86-2);1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione(2451-62-9);Glycols, polyethylene, mono(p-(1,1,3,3-tetramethylbutyl)phenyl) ether(9002-93-1);Lead-titanium-trioxide(12060-00-3) |
| | CRASH PAD | Octamethylcyclotetrasiloxane(556-67-2);Tris(2-chloroethyl) phosphate(115-96-8);Cobalt sulphate(10124-43-3);2-Ethoxyethyl acetate(111-15-9);1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione(2451-62-9);Cyclohexane-1,2-dicarboxylic anhydride(85-42-7);TBBA(79-94-7);Lead(7439-92-1);Lead-monoxide(1317-36-8);Nonoxinol(9016-45-9); Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide(75980-60-8) |
| | DISPLAY | Lead(7439-92-1);Lead titanium zirconium oxide(12626-81-2);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione(2451-62-9);Tris(2-chloroethyl) phosphate(115-96-8);Lead-titanium-trioxide(12060-00-3);Hexahydromethylphthalic-anhydride(25550-51-0) |
| | HEADLINING | C,C'-azodi(formamide)(123-77-3);Tris(2-chloroethyl) phosphate(115-96-8);TBBA(79-94-7);Lead(7439-92-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone(119313-12-1) |
| | SEAT ARM REST | Lead(7439-92-1);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);Lead titanium zirconium oxide(12626-81-2);Tris(2-chloroethyl) phosphate(115-96-8);Melamine(108-78-1);N,N-Dimethylacetamide(127-19-5);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Cobalt sulphate(10124-43-3);C,C'-azodi(formamide)(123-77-3);Cobalt-dinitrate(10141-05-6) |
| | SEAT BELT PRETENTIONER | Cobalt-dinitrate(10141-05-6);Cobalt(II) nitrate hexahydrate(10026-22-9);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Cobalt sulphate(10124-43-3) |
| | STEERING WHEEL GEAR SHIFT LEVER | TBBA(79-94-7);Tris(2-chloroethyl) phosphate(115-96-8);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Lead(7439-92-1) |
| | SWITCHES CONTROLLER | Lead-monoxide(1317-36-8);Lead(7439-92-1) |
| | THE OTHERS | Melamine(108-78-1);Lead(7439-92-1);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);C,C'-azodi(formamide)(123-77-3);1,4-Dioxane(123-91-1);N,N-Dimethylformamide(68-12-2);Tris(2-chloroethyl) phosphate(115-96-8);TBBA(79-94-7);Octamethylcyclotetrasiloxane(556-67-2);Decamethylcyclopentasiloxane(541-02-6) |
| STEERING SUSPENSION | SUSPENSION | Melamine(108-78-1);Cobalt-dinitrate(10141-05-6);4,4'-Isopropylidenediphenol(80-05-7);Lead(7439-92-1);Imidazolidine-2-thione(96-45-7) |
| | STEERING | Melamine(108-78-1);Lead(7439-92-1) |
| BATTERY | BATTERY & MANAGEMENT SYSTEM | TBBA(79-94-7);Lead-monoxide(1317-36-8);Lead(7439-92-1);4,4'-Isopropylidenediphenol(80-05-7);Diboron-trioxide(1303-86-2);Tris(2-chloroethyl) phosphate(115-96-8) |
| | FUEL CELL & MANAGEMENT SYSTEM | |
| THE OTHERS | E-SCOOTER | |
| | CUSTOMIZING PART | |



Movement that inspires

SVHC List

[KIA MOTORS EUROPE] NIRO Plug-in Hybrid (SG2 PHEV)

| Area | Parts | SVHCs present in component articles at greater than 0.1% w/w (CAS No) |
|------|--------------------------------|--|
| BODY | STRUCTURE | Lead(7439-92-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Octamethylcyclotetrasiloxane(556-67-2);Decamethylcyclopentasiloxane(541-02-6);C,C'-azodi(formamide)(123-77-3) |
| | BRAKE | Melamine(108-78-1);C,C'-azodi(formamide)(123-77-3);Diboron-trioxide(1303-86-2);4,4'-Isopropylidenediphenol(80-05-7);Lead(7439-92-1);Lead-monoxide(1317-36-8);Lead-titanium-trioxide(12060-00-3);Octamethylcyclotetrasiloxane(556-67-2);Decamethylcyclopentasiloxane(541-02-6);Dodecamethylcyclohexasiloxane(540-97-6);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5) |
| | BUMPER | Melamine(108-78-1);Boric acid(10043-35-3);Lead(7439-92-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Octamethylcyclotetrasiloxane(556-67-2);Decamethylcyclopentasiloxane(541-02-6);TBBA(79-94-7);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5) |
| | GLASS GLASS MOULDING | Lead(7439-92-1);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Lead-monoxide(1317-36-8) |
| | OUTSIDE LAMP OURSIDE MIRROR | C,C'-azodi(formamide)(123-77-3);Melamine(108-78-1);Phenol, dimethyl-, phosphate (3:1)(25155-23-1);Lead(7439-92-1);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Cobalt-dinitrate(10141-05-6);Boric acid(10043-35-3);1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione(2451-62-9) |
| | WHEEL TIRE | Lead titanium zirconium oxide(12626-81-2);Decamethylcyclopentasiloxane(541-02-6);Dodecamethylcyclohexasiloxane(540-97-6);1,2-Dimethoxyethane(110-71-4);1,3-Propanesultone(1120-71-4);Lead(7439-92-1) |
| | THE OTHERS | Melamine(108-78-1);Lead(7439-92-1);Diboron-trioxide(1303-86-2);Lead titanium zirconium oxide(12626-81-2);Octamethylcyclotetrasiloxane(556-67-2);Decamethylcyclopentasiloxane(541-02-6);C,C'-azodi(formamide)(123-77-3);Di-(2-ethylhexyl)phthalat(117-81-7);Dodecamethylcyclohexasiloxane(540-97-6);Boric acid(10043-35-3);Lead-monoxide(1317-36-8);Alkanes, C14-17, chloro(85535-85-9);N,N-Dimethylacetamide(127-19-5);Imidazolidine-2-thione(96-45-7);2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol(25973-55-1);Bis(4-chlorophenyl) sulfon(80-07-9) |

| | | |
|---------------------|--------------------------|--|
| DOOR SUNROOF | DOOR | C,C'-azodi(formamide)(123-77-3);Phenol, dimethyl-, phosphate (3:1)(25155-23-1);Tris(2-chloroethyl) phosphate(115-96-8);Lead(7439-92-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);TBBA(79-94-7);Cobalt(II) nitrate hexahydrate(10026-22-9);Hexahydromethylphthalic-anhydride(25550-51-0);Lead titanium zirconium oxide(12626-81-2);Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide(75980-60-8) |
| | HOOD | Imidazolidine-2-thione(96-45-7) |
| | SUNROOF | |
| | TRUNK TAIL GATE | Lead(7439-92-1);Lead-monoxide(1317-36-8);Lead-titanium-trioxide(12060-00-3);Diboron-trioxide(1303-86-2);Octamethylcyclotetrasiloxane(556-67-2);Decamethylcyclopentasiloxane(541-02-6) |
| | THE OTHERS | |
| ELECTRIC CONTROL | ELECTRIC CONTROL | Melamine(108-78-1);Lead-monoxide(1317-36-8);Lead(7439-92-1);Diboron-trioxide(1303-86-2);Lead titanium zirconium oxide(12626-81-2);Octamethylcyclotetrasiloxane(556-67-2);Decamethylcyclopentasiloxane(541-02-6);Cobalt chloride(7791-13-1);TBBA(79-94-7);Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide(75980-60-8) |
| | WIRING HARNESS | Lead(7439-92-1);Tris(2-chloroethyl) phosphate(115-96-8);TBBA(79-94-7);Melamine(108-78-1);Lead-monoxide(1317-36-8);C,C'-azodi(formamide)(123-77-3);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Octamethylcyclotetrasiloxane(556-67-2);Tris(2-methoxyethoxy)vinylsilane(1067-53-4);Decamethylcyclopentasiloxane(541-02-6);Diboron-trioxide(1303-86-2) |
| ENGINE ROOM | ENGINE TRANSMISSION | Melamine(108-78-1);Lead(7439-92-1);Di-(2-ethylhexyl)phthalat(117-81-7);Lead-monoxide(1317-36-8);Boric acid(10043-35-3);Octamethylcyclotetrasiloxane(556-67-2);Diboron-trioxide(1303-86-2);Butylbenzylphthalate(85-68-7);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Decamethylcyclopentasiloxane(541-02-6);Dodecamethylcyclohexasiloxane(540-97-6);TBBA(79-94-7);Bis(4-chlorophenyl) sulfon(80-07-9) |
| | HEATER & COOLING UNIT | Tris(2-chloroethyl) phosphate(115-96-8);Hexahydromethylphthalic-anhydride(25550-51-0);C,C'-azodi(formamide)(123-77-3);Lead-monoxide(1317-36-8);Lead(7439-92-1);TBBA(79-94-7);N,N-Dimethylacetamide(127-19-5);Lead-titanium-trioxide(12060-00-3);Diboron-trioxide(1303-86-2) |
| | THE OTHERS | Diboron-trioxide(1303-86-2);Melamine(108-78-1);Lead(7439-92-1);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Octamethylcyclotetrasiloxane(556-67-2);Melamine(108-78-1);N,N-Dimethylformamide(68-12-2);; |
| INTERIOR | AIR BAG | |
| | CONSOLE | Lead(7439-92-1),Lead-monoxide(1317-36-8),2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5),Octamethylcyclotetrasiloxane(556-67-2),Decamethylcyclopentasiloxane(541-02-6),TBBA(79-94-7)Tris(2-chloroethyl) phosphate(115-96-8),Diboron-trioxide(1303-86-2),1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione(2451-62-9),Glycols, polyethylene, mono(p-(1,1,3,3-tetramethylbutyl)phenyl) ether(9002-93-1),Lead-titanium-trioxide(12060-00-3) |

| | | |
|---------------------|---------------------------------|---|
| | CRASH PAD | Octamethylcyclotetrasiloxane(556-67-2);Tris(2-chloroethyl) phosphate(115-96-8);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Lead-monoxide(1317-36-8);2-Ethoxyethyl acetate(111-15-9);1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione(2451-62-9);Cyclohexane-1,2-dicarboxylic anhydride(85-42-7);TBBA(79-94-7);Nonoxinol(9016-45-9);Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide(75980-60-8) |
| | DISPLAY | Lead(7439-92-1);Lead titanium zirconium oxide(12626-81-2);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione(2451-62-9);Tris(2-chloroethyl) phosphate(115-96-8);Hexahydromethylphthalic-anhydride(25550-51-0);Lead-titanium-trioxide(12060-00-3) |
| | HEADLINING | C,C'-azodi(formamide)(123-77-3);TBBA(79-94-7);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8) |
| | SEAT ARM REST | C,C'-azodi(formamide)(123-77-3);Lead(7439-92-1);Tris(2-chloroethyl) phosphate(115-96-8);Melamine(108-78-1);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Cobalt sulphate(10124-43-3);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);N,N-Dimethylacetamide(127-19-5);Cobalt-dinitrate(10141-05-6) |
| | SEAT BELT PRETENTIONER | Cobalt-dinitrate(10141-05-6);Cobalt(II) nitrate hexahydrate(10026-22-9);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Cobalt sulphate(10124-43-3) |
| | STEERING WHEEL GEAR SHIFT LEVER | Tris(2-chloroethyl) phosphate(115-96-8);TBBA(79-94-7);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Lead(7439-92-1) |
| | SWITCHES CONTROLLER | Lead-monoxide(1317-36-8);Lead(7439-92-1) |
| | THE OTHERS | Melamine(108-78-1);Lead(7439-92-1);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);C,C'-azodi(formamide)(123-77-3);N,N-Dimethylformamide(68-12-2);Tris(2-chloroethyl) phosphate(115-96-8);TBBA(79-94-7);Cobalt(II) nitrate hexahydrate(10026-22-9);Octamethylcyclotetrasiloxane(556-67-2);Decamethylcyclopentasiloxane(541-02-6) |
| STEERING SUSPENSION | SUSPENSION | Melamine(108-78-1);Cobalt-dinitrate(10141-05-6);4,4'-Isopropylidenediphenol(80-05-7);Lead(7439-92-1);Imidazolidine-2-thione(96-45-7) |
| | STEERING | Melamine(108-78-1);Lead(7439-92-1) |
| BATTERY | BATTERY & MANAGEMENT SYSTEM | Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Lead(7439-92-1);1-Methyl-2-pyrrolidone(872-50-4);Tris(2-chloroethyl) phosphate(115-96-8);Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide(75980-60-8) |
| | FUEL CELL & MANAGEMENT SYSTEM | |
| THE OTHERS | E-SCOOTER | |
| | CUSTOMIZING PART | |

No specific safe use information is required – follow General Safe Use Information for Articles.