



SVHC List

[KIA MOTORS EUROPE] NIRO Hybrid (SG2 HEV)

Area	Parts	SVHCs present in component articles at greater than 0.1% w/w (CAS No)
BODY	STRUCTURE	Lead(7439-92-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Octamethylcyclotetrasiloxane(556-67-2);Decamethylcyclopentasiloxane(541-02-6);C,C'-azodi(formamide)(123-77-3)
	BRAKE	Melamine(108-78-1);C,C'-azodi(formamide)(123-77-3);Diboron-trioxide(1303-86-2);4,4'-Isopropylidenediphenol(80-05-7);Lead(7439-92-1);Lead-monoxide(1317-36-8);Lead-titanium-trioxide(12060-00-3);Octamethylcyclotetrasiloxane(556-67-2);Decamethylcyclopentasiloxane(541-02-6);Dodecamethylcyclohexasiloxane(540-97-6);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5)
	BUMPER	Melamine(108-78-1);Boric acid(10043-35-3);Lead(7439-92-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Octamethylcyclotetrasiloxane(556-67-2);Decamethylcyclopentasiloxane(541-02-6);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);TBBA(79-94-7)
	GLASS GLASS MOULDING	Lead(7439-92-1);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Lead-monoxide(1317-36-8)
	OUTSIDE LAMP OUTSIDE MIRROR	C,C'-azodi(formamide)(123-77-3);Melamine(108-78-1);Phenol, dimethyl-, phosphate (3:1)(25155-23-1);Lead(7439-92-1);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Cobalt-dinitrate(10141-05-6);Boric acid(10043-35-3);Cobalt(II) nitrate hexahydrate(10026-22-9)
	WHEEL TIRE	Lead titanium zirconium oxide(12626-81-2);Decamethylcyclopentasiloxane(541-02-6);Dodecamethylcyclohexasiloxane(540-97-6);1,2-Dimethoxyethane(110-71-4);1,3-Propanesultone(1120-71-4);Lead(7439-92-1)
	THE OTHERS	Melamine(108-78-1);Lead(7439-92-1);Diboron-trioxide(1303-86-2);Lead titanium zirconium oxide(12626-81-2);Octamethylcyclotetrasiloxane(556-67-2);Decamethylcyclopentasiloxane(541-02-6);C,C'-azodi(formamide)(123-77-3);Dodecamethylcyclohexasiloxane(540-97-6);Lead-monoxide(1317-36-8);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Alkanes, C14-17, chloro(85535-85-9);N,N-Dimethylacetamide(127-19-5);Imidazolidine-2-thione(96-45-7);2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol(25973-55-1);Boric acid(10043-35-3)

DOOR SUNROOF	DOOR	C,C'-azodi(formamide)(123-77-3);Phenol, dimethyl-, phosphate (3:1)(25155-23-1);Tris(2-chloroethyl) phosphate(115-96-8);Lead(7439-92-1);Lead-monoxide(1317-36-8);6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol(119-47-1);Lead-titanium-trioxide(12060-00-3);TBBA(79-94-7);Cobalt(II) nitrate hexahydrate(10026-22-9);Diboron-trioxide(1303-86-2);Hexahydromethylphthalic-anhydride(25550-51-0);Lead titanium zirconium oxide(12626-81-2)
	HOOD	Imidazolidine-2-thione(96-45-7)
	SUNROOF	C,C'-azodi(formamide)(123-77-3);Lead(7439-92-1);Cobalt(II) nitrate hexahydrate(10026-22-9);Lead-monoxide(1317-36-8);Octamethylcyclotetrasiloxane(556-67-2);Decamethylcyclopentasiloxane(541-02-6)
	TRUNK TAIL GATE	Lead(7439-92-1);Lead-monoxide(1317-36-8);Lead-titanium-trioxide(12060-00-3);Diboron-trioxide(1303-86-2);Octamethylcyclotetrasiloxane(556-67-2);Decamethylcyclopentasiloxane(541-02-6)
	THE OTHERS	
ELECTRIC CONTROL	ELECTRIC CONTROL	Melamine(108-78-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Lead(7439-92-1);Lead titanium zirconium oxide(12626-81-2);Octamethylcyclotetrasiloxane(556-67-2);Decamethylcyclopentasiloxane(541-02-6);4-Methylcyclohexyl-1,6-dicarboxylic acid anhydride(19438-60-9);Cobalt chloride(7791-13-1);TBBA(79-94-7)
	WIRING HARNESS	TBBA(79-94-7);Lead(7439-92-1);Melamine(108-78-1);C,C'-azodi(formamide)(123-77-3);Lead-monoxide(1317-36-8);Octamethylcyclotetrasiloxane(556-67-2);Decamethylcyclopentasiloxane(541-02-6);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5)
ENGINE ROOM	ENGINE TRANSMISSION	Melamine(108-78-1);Lead(7439-92-1);Di-(2-ethylhexyl)phthalat(117-81-7);Lead-monoxide(1317-36-8);Boric acid(10043-35-3);Octamethylcyclotetrasiloxane(556-67-2);Diboron-trioxide(1303-86-2);Butylbenzylphthalate(85-68-7);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);1-Methyl-2-pyrrolidone(872-50-4);Decamethylcyclopentasiloxane(541-02-6);Dodecamethylcyclohexasiloxane(540-97-6);TBBA(79-94-7)
	HEATER & COOLING UNIT	Hexahydromethylphthalic-anhydride(25550-51-0);C,C'-azodi(formamide)(123-77-3);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Lead(7439-92-1);Tris(2-chloroethyl) phosphate(115-96-8)
	THE OTHERS	Diboron-trioxide(1303-86-2);Melamine(108-78-1);Lead(7439-92-1);Lead-monoxide(1317-36-8);Decamethylcyclopentasiloxane(541-02-6);Dodecamethylcyclohexasiloxane(540-97-6);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Tris(2-methoxyethoxy)vinylsilane(1067-53-4);Octamethylcyclotetrasiloxane(556-67-2)
INTERIOR	AIR BAG	Lead(7439-92-1);Lead titanium zirconium oxide(12626-81-2)
	CONSOLE	Lead(7439-92-1);Lead-monoxide(1317-36-8);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Octamethylcyclotetrasiloxane(556-67-2);Decamethylcyclopentasiloxane(541-02-6);TBBA(79-94-7);Tris(2-chloroethyl) phosphate(115-96-8);Diboron-trioxide(1303-86-2);1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione(2451-62-9);Glycols, polyethylene, mono(p-(1,1,3,3-tetramethylbutyl)phenyl) ether(9002-93-1);Lead-titanium-trioxide(12060-00-3)

	CRASH PAD	Octamethylcyclotetrasiloxane(556-67-2);Tris(2-chloroethyl) phosphate(115-96-8);Cobalt sulphate(10124-43-3);2-Ethoxyethyl acetate(111-15-9);1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione(2451-62-9);Cyclohexane-1,2-dicarboxylic anhydride(85-42-7);TBBA(79-94-7);Lead(7439-92-1);Lead-monoxide(1317-36-8);Nonoxinol(9016-45-9)
	DISPLAY	Lead(7439-92-1);Lead titanium zirconium oxide(12626-81-2);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione(2451-62-9);Tris(2-chloroethyl) phosphate(115-96-8);Lead-titanium-trioxide(12060-00-3);Hexahydromethylphthalic-anhydride(25550-51-0)
	HEADLINING	C,C'-azodi(formamide)(123-77-3);Tris(2-chloroethyl) phosphate(115-96-8);TBBA(79-94-7);Lead(7439-92-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone(119313-12-1)
	SEAT ARM REST	Lead(7439-92-1);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);Lead titanium zirconium oxide(12626-81-2);Tris(2-chloroethyl) phosphate(115-96-8);Melamine(108-78-1);N,N-Dimethylacetamide(127-19-5);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Cobalt sulphate(10124-43-3);C,C'-azodi(formamide)(123-77-3);Cobalt-dinitrate(10141-05-6)
	SEAT BELT PRETENTIONER	Cobalt-dinitrate(10141-05-6);Cobalt(II) nitrate hexahydrate(10026-22-9);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Cobalt sulphate(10124-43-3)
	STEERING WHEEL GEAR SHIFT LEVER	TBBA(79-94-7);Tris(2-chloroethyl) phosphate(115-96-8);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Lead(7439-92-1)
	SWITCHES CONTROLLER	Lead-monoxide(1317-36-8);Lead(7439-92-1)
	THE OTHERS	Melamine(108-78-1);Lead(7439-92-1);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);C,C'-azodi(formamide)(123-77-3);1,4-Dioxane(123-91-1);N,N-Dimethylformamide(68-12-2);Tris(2-chloroethyl) phosphate(115-96-8);TBBA(79-94-7);Octamethylcyclotetrasiloxane(556-67-2);Decamethylcyclopentasiloxane(541-02-6)
STEERING SUSPENSION	SUSPENSION	Melamine(108-78-1);Cobalt-dinitrate(10141-05-6);4,4'-Isopropylidenediphenol(80-05-7);Lead(7439-92-1);Imidazolidine-2-thione(96-45-7)
	STEERING	Melamine(108-78-1);Lead(7439-92-1)
BATTERY	BATTERY & MANAGEMENT SYSTEM	TBBA(79-94-7);Lead-monoxide(1317-36-8);Lead(7439-92-1);4,4'-Isopropylidenediphenol(80-05-7);Diboron-trioxide(1303-86-2);Tris(2-chloroethyl) phosphate(115-96-8)
	FUEL CELL & MANAGEMENT SYSTEM	
THE OTHERS	E-SCOOTER	
	CUSTOMIZING PART	

No specific safe use information is required – follow General Safe Use Information for Articles.