



Movement that inspires

SVHC List

[KIA MOTORS EUROPE] SPORTAGE (NQ5)

Area	Parts	SVHCs present in component articles at greater than 0.1% w/w (CAS No)
BODY	STRUCTURE	C,C'-azodi(formamide)(123-77-3);Dicyclohexyl-phthalate(84-61-7)
	BRAKE	Melamine(108-78-1);Tris(nonylphenyl)phosphite(26523-78-4);Lead-monoxide(1317-36-8);TBBA(79-94-7);Octamethylcyclotetrasiloxane(556-67-2);Cobalt(II) nitrate hexahydrate(10026-22-9);2-Methylimidazole(693-98-1);C,C'-azodi(formamide)(123-77-3);Decamethylcyclopentasiloxane(541-02-6);Dodecamethylcyclohexasiloxane(540-97-6);Glycols, polyethylene, mono((1,1,3,3-tetramethylbutyl)phenyl) ether(9036-19-5)
	BUMPER	Melamine(108-78-1);TBBA(79-94-7);Octamethylcyclotetrasiloxane(556-67-2);Lead-monoxide(1317-36-8);Decamethylcyclopentasiloxane(541-02-6)
	GLASS GLASS MOULDING	Lead-monoxide(1317-36-8);Alkanes, C14-17, chloro(85535-85-9);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5)
	OUTSIDE LAMP OURSIDE MIRROR	Melamine(108-78-1);Lead-monoxide(1317-36-8);Phenol, dimethyl-, phosphate (3:1)(25155-23-1);Octamethylcyclotetrasiloxane(556-67-2);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Decamethylcyclopentasiloxane(541-02-6);C,C'-azodi(formamide)(123-77-3)
	WHEEL TIRE	1,2-Dimethoxyethane(110-71-4)
	THE OTHERS	Melamine(108-78-1);Lead titanium zirconium oxide(12626-81-2);TBBA(79-94-7);Lead-monoxide(1317-36-8);Lead-titanium-trioxide(12060-00-3);Phenol, dimethyl-, phosphate (3:1)(25155-23-1);N,N-Dimethylacetamide(127-19-5);C,C'-azodi(formamide)(123-77-3);Bis(2-(2-methoxyethoxy)ethyl)ether(143-24-8);Imidazolidine-2-thione(96-45-7);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol(25973-55-1)
	DOOR SUNROOF	DOOR
HOOD		
SUNROOF		TBBA(79-94-7);Lead-monoxide(1317-36-8);Imidazolidine-2-thione(96-45-7);C,C'-azodi(formamide)(123-77-3)
TRUNK TAIL GATE		TBBA(79-94-7);Lead-monoxide(1317-36-8);Lead-titanium-trioxide(12060-00-3);C,C'-azodi(formamide)(123-77-3)
THE OTHERS		

ELECTRIC CONTROL	ELECTRIC CONTROL	Melamine(108-78-1);Lead-monoxide(1317-36-8);Lead-titanium-trioxide(12060-00-3);TBBA(79-94-7);Octamethylcyclotetrasiloxane(556-67-2);Tris(2-chloroethyl) phosphate(115-96-8);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);1,2-Dimethoxyethane(110-71-4);Decamethylcyclopentasiloxane(541-02-6);Dicyclohexyl-phthalate(84-61-7);4,4'-Isopropylidenediphenol(80-05-7)
	WIRING HARNESS	Melamine(108-78-1);Tris(2-chloroethyl) phosphate(115-96-8);TBBA(79-94-7);Octamethylcyclotetrasiloxane(556-67-2);Lead-monoxide(1317-36-8);Lead titanium zirconium oxide(12626-81-2);Decamethylcyclopentasiloxane(541-02-6);C,C'-azodi(formamide)(123-77-3)
ENGINE ROOM	ENGINE TRANSMISSION	Melamine(108-78-1);Tris(2-chloroethyl) phosphate(115-96-8);Lead titanium zirconium oxide(12626-81-2);Octamethylcyclotetrasiloxane(556-67-2);Lead-monoxide(1317-36-8);N,N-Dimethylacetamide(127-19-5);Lead-titanium-trioxide(12060-00-3);Tris(nonylphenyl)phosphite(26523-78-4);Decamethylcyclopentasiloxane(541-02-6);Imidazolidine-2-thione(96-45-7);Ethylenediamine(107-15-3);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Cobalt(II) nitrate hexahydrate(10026-22-9);Dodecamethylcyclohexasiloxane(540-97-6)
	HEATER & COOLING UNIT	Melamine(108-78-1);Lead-monoxide(1317-36-8);Lead-titanium-trioxide(12060-00-3);Tris(2-chloroethyl) phosphate(115-96-8);TBBA(79-94-7);Hexahydromethylphthalic-anhydride(25550-51-0)
	THE OTHERS	Melamine(108-78-1);Lead-monoxide(1317-36-8);Octamethylcyclotetrasiloxane(556-67-2);Imidazolidine-2-thione(96-45-7);C,C'-azodi(formamide)(123-77-3);Decamethylcyclopentasiloxane(541-02-6);Bis(4-chlorophenyl) sulfon(80-07-9)
INTERIOR	AIR BAG	
	CONSOLE	Lead-monoxide(1317-36-8);TBBA(79-94-7);Lead-titanium-trioxide(12060-00-3);Glycols, polyethylene, mono(p-(1,1,3,3-tetramethylbutyl)phenyl) ether(9002-93-1);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5)
	CRASH PAD	TBBA(79-94-7);Tris(2-chloroethyl) phosphate(115-96-8);Lead-monoxide(1317-36-8);Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide(75980-60-8)
	DISPLAY	Lead-monoxide(1317-36-8);Lead titanium zirconium oxide(12626-81-2);Tris(2-chloroethyl) phosphate(115-96-8);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione(2451-62-9);Hexahydromethylphthalic-anhydride(25550-51-0)
	HEADLINING	TBBA(79-94-7);Tris(2-chloroethyl) phosphate(115-96-8);Lead-monoxide(1317-36-8);Melamine(108-78-1);C,C'-azodi(formamide)(123-77-3);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Cobalt(II) nitrate hexahydrate(10026-22-9);2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone(119313-12-1)
	SEAT ARM REST	Lead-monoxide(1317-36-8);TBBA(79-94-7);Tris(2-chloroethyl) phosphate(115-96-8);Lead titanium zirconium oxide(12626-81-2);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione(2451-62-9);C,C'-azodi(formamide)(123-77-3);Cobalt-sulfate-heptahydrate(10026-24-1)
	SEAT BELT PRETENTIONER	Cobalt(II) nitrate hexahydrate(10026-22-9);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5)

	STEERING WHEEL GEAR SHIFT LEVER	N,N,N',N'-Tetramethyl-4,4'-methylenedianiline(101-61-1);Lead-monoxide(1317-36-8);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);C,C'-azodi(formamide)(123-77-3)
	SWITCHES CONTROLLER	Lead-monoxide(1317-36-8)
	THE OTHERS	Lead-monoxide(1317-36-8);N,N-Dimethylformamide(68-12-2);Lead-titanium-trioxide(12060-00-3);TBBA(79-94-7);N,N-Dimethylacetamide(127-19-5);1,4-Dioxane(123-91-1);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Cobalt-sulfate-heptahydrate(10026-24-1);Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide(75980-60-8)
STEERING SUSPENSION	SUSPENSION	Melamine(108-78-1);Tris(nonylphenyl)phosphite(26523-78-4);Melamine(108-78-1);Tris(2-chloroethyl) phosphate(115-96-8);Lead titanium zirconium oxide(12626-81-2);Octamethylcyclotetrasiloxane(556-67-2);Lead-monoxide(1317-36-8);N,N-Dimethylacetamide(127-19-5)
	STEERING	
BATTERY	BATTERY & MANAGEMENT SYSTEM	
	FUEL CELL & MANAGEMENT SYSTEM	
THE OTHERS	E-SCOOTER	
	CUSTOMIZING PART	

No specific safe use information is required – follow General Safe Use Information for Articles.



Movement that inspires

SVHC List

[KIA MOTORS EUROPE] SPORTAGE Hybrid (NQ5 HEV)

Area	Parts	SVHCs present in component articles at greater than 0.1% w/w (CAS No)
BODY	STRUCTURE	C,C'-azodi(formamide)(123-77-3);Dicyclohexyl-phthalate(84-61-7)
	BRAKE	Melamine(108-78-1);Tris(nonylphenyl)phosphite(26523-78-4);Lead-monoxide(1317-36-8);TBBA(79-94-7);Octamethylcyclotetrasiloxane(556-67-2);Cobalt(II) nitrate hexahydrate(10026-22-9);2-Methylimidazole(693-98-1);C,C'-azodi(formamide)(123-77-3);Decamethylcyclopentasiloxane(541-02-6);Dodecamethylcyclohexasiloxane(540-97-6);Glycols, polyethylene, mono((1,1,3,3-tetramethylbutyl)phenyl) ether(9036-19-5);4,4'-Isopropylidenediphenol(80-05-7);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5)
	BUMPER	Melamine(108-78-1);TBBA(79-94-7);Octamethylcyclotetrasiloxane(556-67-2);Lead-monoxide(1317-36-8);Decamethylcyclopentasiloxane(541-02-6);Lead(7439-92-1);Diboron-trioxide(1303-86-2);2-Ethoxyethyl acetate(111-15-9);Imidazolidine-2-thione(96-45-7)
	GLASS GLASS MOULDING	Lead-monoxide(1317-36-8);Alkanes, C14-17, chloro(85535-85-9);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);C,C'-azodi(formamide)(123-77-3)
	OUTSIDE LAMP OURSIDE MIRROR	Melamine(108-78-1);Lead-monoxide(1317-36-8);Phenol, dimethyl-, phosphate (3:1)(25155-23-1);Octamethylcyclotetrasiloxane(556-67-2);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Decamethylcyclopentasiloxane(541-02-6);C,C'-azodi(formamide)(123-77-3);Lead(7439-92-1);Boric acid(10043-35-3);Diboron-trioxide(1303-86-2);1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione(2451-62-9);2-Ethoxyethyl acetate(111-15-9)
	WHEEL TIRE	1,2-Dimethoxyethane(110-71-4)
	THE OTHERS	Melamine(108-78-1);Lead titanium zirconium oxide(12626-81-2);TBBA(79-94-7);Lead-monoxide(1317-36-8);Lead-titanium-trioxide(12060-00-3);Phenol, dimethyl-, phosphate (3:1)(25155-23-1);N,N-Dimethylacetamide(127-19-5);C,C'-azodi(formamide)(123-77-3);Bis(2-(2-methoxyethoxy)ethyl)ether(143-24-8);Imidazolidine-2-thione(96-45-7);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol(25973-55-1);Diboron-trioxide(1303-86-2);Lead(7439-92-1); Bis(4-chlorophenyl) sulfon(80-07-9)
DOOR SUNROOF	DOOR	Tris(2-chloroethyl) phosphate(115-96-8);Lead-monoxide(1317-36-8);Lead-titanium-trioxide(12060-00-3);TBBA(79-94-7);Imidazolidine-2-thione(96-45-7);C,C'-azodi(formamide)(123-77-3);6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol(119-47-1);Hexahydromethylphthalic-

		anhydride(25550-51-0);Cobalt(II) nitrate hexahydrate(10026-22-9);Lead(7439-92-1);Lead titanium zirconium oxide(12626-81-2)
	HOOD	Imidazolidine-2-thione(96-45-7)
	SUNROOF	TBBA(79-94-7);Lead-monoxide(1317-36-8);Imidazolidine-2-thione(96-45-7);C,C'-azodi(formamide)(123-77-3);Diocetyl tin dilaurate(3648-18-8)
	TRUNK TAIL GATE	TBBA(79-94-7);Lead-monoxide(1317-36-8);Lead-titanium-trioxide(12060-00-3);C,C'-azodi(formamide)(123-77-3);Octamethylcyclotetrasiloxane(556-67-2);Decamethylcyclopentasiloxane(541-02-6)
	THE OTHERS	
ELECTRIC CONTROL	ELECTRIC CONTROL	Melamine(108-78-1);Lead-monoxide(1317-36-8);Lead-titanium-trioxide(12060-00-3);TBBA(79-94-7);Octamethylcyclotetrasiloxane(556-67-2);Tris(2-chloroethyl) phosphate(115-96-8);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);1,2-Dimethoxyethane(110-71-4);Decamethylcyclopentasiloxane(541-02-6);Dicyclohexyl-phthalate(84-61-7);4,4'-Isopropylidenediphenol(80-05-7);Lead(7439-92-1);Diboron-trioxide(1303-86-2);1-Methyl-2-pyrrolidone(872-50-4);Alkanes, C16-35, chloro(85049-26-9);2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone(119313-12-1);Lead titanium zirconium oxide(12626-81-2)
	WIRING HARNESS	Melamine(108-78-1);Tris(2-chloroethyl) phosphate(115-96-8);TBBA(79-94-7);Octamethylcyclotetrasiloxane(556-67-2);Lead-monoxide(1317-36-8);Lead titanium zirconium oxide(12626-81-2);Decamethylcyclopentasiloxane(541-02-6);C,C'-azodi(formamide)(123-77-3);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5)
ENGINE ROOM	ENGINE TRANSMISSION	Melamine(108-78-1);Tris(2-chloroethyl) phosphate(115-96-8);Lead titanium zirconium oxide(12626-81-2);Octamethylcyclotetrasiloxane(556-67-2);Lead-monoxide(1317-36-8);N,N-Dimethylacetamide(127-19-5);Lead-titanium-trioxide(12060-00-3);Tris(nonylphenyl)phosphite(26523-78-4);Decamethylcyclopentasiloxane(541-02-6);Imidazolidine-2-thione(96-45-7);Ethylenediamine(107-15-3);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Cobalt(II) nitrate hexahydrate(10026-22-9);Dodecamethylcyclohexasiloxane(540-97-6);Diboron-trioxide(1303-86-2);Lead(7439-92-1);Cobalt sulphate(10124-43-3);2-Methylimidazole(693-98-1);C,C'-azodi(formamide)(123-77-3);Bis(4-chlorophenyl) sulfon(80-07-9)
	HEATER & COOLING UNIT	Melamine(108-78-1);Lead-monoxide(1317-36-8);Lead-titanium-trioxide(12060-00-3);Tris(2-chloroethyl) phosphate(115-96-8);TBBA(79-94-7);Hexahydromethylphthalic-anhydride(25550-51-0);Diboron-trioxide(1303-86-2);Lead(7439-92-1);Lead titanium zirconium oxide(12626-81-2);Cobalt(II) nitrate hexahydrate(10026-22-9);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5)
	THE OTHERS	Melamine(108-78-1);Lead-monoxide(1317-36-8);Octamethylcyclotetrasiloxane(556-67-2);Imidazolidine-2-thione(96-45-7);C,C'-azodi(formamide)(123-77-3);Decamethylcyclopentasiloxane(541-02-6);Lead(7439-92-1);Diboron-trioxide(1303-86-2);Tris(2-methoxyethoxy)vinylsilane(1067-53-4);Phenol, dodecyl-, branched(121158-58-5);Lead titanium zirconium oxide(12626-81-2);Cobalt-dinitrate(10141-05-6)
INTERIOR	AIR BAG	
	CONSOLE	Lead-monoxide(1317-36-8);TBBA(79-94-7);Lead-titanium-trioxide(12060-00-3);Glycols, polyethylene, mono(p-(1,1,3,3-tetramethylbutyl)phenyl) ether(9002-93-1);2-Methyl-1-(4-

		methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Lead(7439-92-1);Lead titanium zirconium oxide(12626-81-2);Diboron-trioxide(1303-86-2);Melamine(108-78-1)
	CRASH PAD	TBBA(79-94-7);Tris(2-chloroethyl) phosphate(115-96-8);Lead-monoxide(1317-36-8);Lead(7439-92-1);C,C'-azodi(formamide)(123-77-3);Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide(75980-60-8);Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide(75980-60-8)
	DISPLAY	Lead-monoxide(1317-36-8);Lead titanium zirconium oxide(12626-81-2);Tris(2-chloroethyl) phosphate(115-96-8);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione(2451-62-9);Hexahydromethylphthalic-anhydride(25550-51-0);Diboron-trioxide(1303-86-2);Lead(7439-92-1);Lead-titanium-trioxide(12060-00-3);Octamethylcyclotetrasiloxane(556-67-2)
	HEADLINING	TBBA(79-94-7);Tris(2-chloroethyl) phosphate(115-96-8);Lead-monoxide(1317-36-8);Melamine(108-78-1);C,C'-azodi(formamide)(123-77-3);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Cobalt(II) nitrate hexahydrate(10026-22-9);2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone(119313-12-1);Diboron-trioxide(1303-86-2);Lead titanium zirconium oxide(12626-81-2)
	SEAT ARM REST	Lead-monoxide(1317-36-8);TBBA(79-94-7);Tris(2-chloroethyl) phosphate(115-96-8);Lead titanium zirconium oxide(12626-81-2);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione(2451-62-9);C,C'-azodi(formamide)(123-77-3);Cobalt-sulfate-heptahydrate(10026-24-1);Diboron-trioxide(1303-86-2);Lead(7439-92-1);Alkanes, C14-17, chloro(85535-85-9);Cobalt sulphate(10124-43-3)
	SEAT BELT PRETENTIONER	Cobalt(II) nitrate hexahydrate(10026-22-9);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5)
	STEERING WHEEL GEAR SHIFT LEVER	N,N,N',N'-Tetramethyl-4,4'-methylenedianiline(101-61-1);Lead-monoxide(1317-36-8);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);C,C'-azodi(formamide)(123-77-3);Diboron-trioxide(1303-86-2);Lead(7439-92-1);Cobalt-dinitrate(10141-05-6);Cobalt sulphate(10124-43-3)
	SWITCHES CONTROLLER	Lead-monoxide(1317-36-8);Lead(7439-92-1)
	THE OTHERS	Lead-monoxide(1317-36-8);N,N-Dimethylformamide(68-12-2);Lead-titanium-trioxide(12060-00-3);TBBA(79-94-7);N,N-Dimethylacetamide(127-19-5);1,4-Dioxane(123-91-1);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Cobalt-sulfate-heptahydrate(10026-24-1);Lead(7439-92-1);Diboron-trioxide(1303-86-2);Octamethylcyclotetrasiloxane(556-67-2);Decamethylcyclopentasiloxane(541-02-6);Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide(75980-60-8)
STEERING SUSPENSION	SUSPENSION	Melamine(108-78-1);Tris(nonylphenyl)phosphite(26523-78-4)
	STEERING	Melamine(108-78-1);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5)
BATTERY	BATTERY & MANAGEMENT SYSTEM	C,C'-azodi(formamide)(123-77-3);Octamethylcyclotetrasiloxane(556-67-2)
	FUEL CELL & MANAGEMENT SYSTEM	
THE OTHERS	E-SCOOTER	
	CUSTOMIZING PART	

No specific safe use information is required – follow General Safe Use Information for Articles.



Movement that inspires

SVHC List

[KIA MOTORS EUROPE] SPORTAGE Plug-in Hybrid (NQ5 PHEV)

Area	Parts	SVHCs present in component articles at greater than 0.1% w/w (CAS No)
BODY	STRUCTURE	C,C'-azodi(formamide)(123-77-3);Dicyclohexyl-phthalate(84-61-7)
	BRAKE	Melamine(108-78-1);Lead(7439-92-1);Cobalt(II) nitrate hexahydrate(10026-22-9);Tris(nonylphenyl)phosphite(26523-78-4);Di-(2-ethylhexyl)phthalat(117-81-7);2-Methylimidazole(693-98-1);C,C'-azodi(formamide)(123-77-3);Diboron-trioxide(1303-86-2);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);4,4'-Isopropylidenediphenol(80-05-7);Octamethylcyclotetrasiloxane(556-67-2);Decamethylcyclopentasiloxane(541-02-6);Dodecamethylcyclohexasiloxane(540-97-6);Glycols, polyethylene, mono((1,1,3,3-tetramethylbutyl)phenyl) ether(9036-19-5)
	BUMPER	Melamine(108-78-1);TBBA(79-94-7);Lead(7439-92-1);C,C'-azodi(formamide)(123-77-3);Octamethylcyclotetrasiloxane(556-67-2);Decamethylcyclopentasiloxane(541-02-6);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);2-Ethoxyethyl acetate(111-15-9);Imidazolidine-2-thione(96-45-7)
	GLASS GLASS MOULDING	Lead(7439-92-1);Imidazolidine-2-thione(96-45-7);C,C'-azodi(formamide)(123-77-3);Octamethylcyclotetrasiloxane(556-67-2);Alkanes, C14-17, chloro(85535-85-9);Diboron-trioxide(1303-86-2);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Lead-monoxide(1317-36-8)
	OUTSIDE LAMP OURSIDE MIRROR	C,C'-azodi(formamide)(123-77-3);Melamine(108-78-1);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Lead-monoxide(1317-36-8);Lead(7439-92-1);Phenol, dimethyl-, phosphate (3:1)(25155-23-1);Diboron-trioxide(1303-86-2);Octamethylcyclotetrasiloxane(556-67-2);Decamethylcyclopentasiloxane(541-02-6);Boric acid(10043-35-3);1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione(2451-62-9);2-Ethoxyethyl acetate(111-15-9)
	WHEEL TIRE	
	THE OTHERS	Melamine(108-78-1);Octamethylcyclotetrasiloxane(556-67-2);Decamethylcyclopentasiloxane(541-02-6);C,C'-azodi(formamide)(123-77-3);Lead(7439-92-1);Lead-monoxide(1317-36-8);TBBA(79-94-7);Diboron-trioxide(1303-86-2);N,N-Dimethylacetamide(127-19-5);Imidazolidine-2-thione(96-45-7);2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol(25973-55-1);Phenol, dimethyl-, phosphate (3:1)(25155-23-1)
DOOR SUNROOF	DOOR	Lead(7439-92-1);Imidazolidine-2-thione(96-45-7);C,C'-azodi(formamide)(123-77-3);Tris(2-chloroethyl) phosphate(115-96-

		8);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);Hexahydromethylphthalic-anhydride(25550-51-0);Cobalt(II) nitrate hexahydrate(10026-22-9);TBBA(79-94-7);Lead titanium zirconium oxide(12626-81-2)
	HOOD	Imidazolidine-2-thione(96-45-7)
	SUNROOF	Lead(7439-92-1);Imidazolidine-2-thione(96-45-7);C,C'-azodi(formamide)(123-77-3);TBBA(79-94-7);Lead-monoxide(1317-36-8);Diocetyl tin dilaurate(3648-18-8)
	TRUNK TAIL GATE	TBBA(79-94-7);Cobalt-dinitrate(10141-05-6);Lead(7439-92-1);Lead-monoxide(1317-36-8);Lead-titanium-trioxide(12060-00-3);Diboron-trioxide(1303-86-2);Octamethylcyclotetrasiloxane(556-67-2);Decamethylcyclopentasiloxane(541-02-6);Melamine(108-78-1)
	THE OTHERS	
ELECTRIC CONTROL	ELECTRIC CONTROL	Melamine(108-78-1);Lead(7439-92-1);Lead-monoxide(1317-36-8);Lead-titanium-trioxide(12060-00-3);Diboron-trioxide(1303-86-2);1,2-Dimethoxyethane(110-71-4);TBBA(79-94-7);Dicyclohexyl-phthalate(84-61-7);4,4'-Isopropylidenediphenol(80-05-7);Octamethylcyclotetrasiloxane(556-67-2);Decamethylcyclopentasiloxane(541-02-6);Tris(2-chloroethyl) phosphate(115-96-8);1-Methyl-2-pyrrolidone(872-50-4);Alkanes, C16-35, chloro(85049-26-9);2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone(119313-12-1);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Lead titanium zirconium oxide(12626-81-2)
	WIRING HARNESS	Melamine(108-78-1);TBBA(79-94-7);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Lead(7439-92-1);C,C'-azodi(formamide)(123-77-3);Octamethylcyclotetrasiloxane(556-67-2);Decamethylcyclopentasiloxane(541-02-6);Tris(2-methoxyethoxy)vinylsilane(1067-53-4);Tris(2-chloroethyl) phosphate(115-96-8);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Lead titanium zirconium oxide(12626-81-2)
ENGINE ROOM	ENGINE TRANSMISSION	Melamine(108-78-1);Lead(7439-92-1);Octamethylcyclotetrasiloxane(556-67-2);Diboron-trioxide(1303-86-2);6,6'-Di-tert-butyl-2,2'-methylene-di-p-cresol(119-47-1);Decamethylcyclopentasiloxane(541-02-6);Dodecamethylcyclohexasiloxane(540-97-6);Lead-monoxide(1317-36-8);1-Methyl-2-pyrrolidone(872-50-4);Carbonic acid, cobalt(2+) salt (1:1)(513-79-1);Refractory ceramic fibres(142844-00-6);Lead titanium zirconium oxide(12626-81-2);Boric acid(10043-35-3);TBBA(79-94-7);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Tris(nonylphenyl)phosphite(26523-78-4);Tris(2-methoxyethoxy)vinylsilane(1067-53-4);Cobalt sulphate(10124-43-3);2-Methylimidazole(693-98-1);C,C'-azodi(formamide)(123-77-3);Bis(4-chlorophenyl) sulfon(80-07-9)
	HEATER & COOLING UNIT	Lead-monoxide(1317-36-8);Hexahydromethylphthalic-anhydride(25550-51-0);Lead-titanium-trioxide(12060-00-3);Diboron-trioxide(1303-86-2);Lead(7439-92-1);Tris(2-chloroethyl) phosphate(115-96-8);TBBA(79-94-7);Lead titanium zirconium oxide(12626-81-2);Cobalt(II) nitrate hexahydrate(10026-22-9);Melamine(108-78-1);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5)
	THE OTHERS	Melamine(108-78-1);Lead(7439-92-1);Lead-monoxide(1317-36-8);Imidazolidine-2-thione(96-45-7);Diboron-trioxide(1303-86-2);Boric acid(10043-35-3);Octamethylcyclotetrasiloxane(556-67-2);Tris(2-methoxyethoxy)vinylsilane(1067-53-4);Phenol, dodecyl-, branched(121158-58-5);Decamethylcyclopentasiloxane(541-02-6);Lead titanium zirconium oxide(12626-81-2);Cobalt-dinitrate(10141-05-6)

INTERIOR	AIR BAG	
	CONSOLE	Lead(7439-92-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);TBBA(79-94-7);Lead titanium zirconium oxide(12626-81-2);Lead-titanium-trioxide(12060-00-3);Glycols, polyethylene, mono(p-(1,1,3,3-tetramethylbutyl)phenyl) ether(9002-93-1);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Melamine(108-78-1)
	CRASH PAD	TBBA(79-94-7);Tris(2-chloroethyl) phosphate(115-96-8);Lead-monoxide(1317-36-8);Lead(7439-92-1);C,C'-azodi(formamide)(123-77-3);Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide(75980-60-8)
	DISPLAY	Diboron-trioxide(1303-86-2);Lead(7439-92-1);Lead-monoxide(1317-36-8);Lead titanium zirconium oxide(12626-81-2);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione(2451-62-9);Tris(2-chloroethyl) phosphate(115-96-8);Lead-titanium-trioxide(12060-00-3);Octamethylcyclotetrasiloxane(556-67-2)
	HEADLINING	C,C'-azodi(formamide)(123-77-3);Tris(2-chloroethyl) phosphate(115-96-8);TBBA(79-94-7);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Lead-monoxide(1317-36-8);Melamine(108-78-1);Diboron-trioxide(1303-86-2);Lead titanium zirconium oxide(12626-81-2)
	SEAT ARM REST	Diboron-trioxide(1303-86-2);Lead(7439-92-1);Lead-monoxide(1317-36-8);1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione(2451-62-9);TBBA(79-94-7);Lead titanium zirconium oxide(12626-81-2);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Alkanes, C14-17, chloro(85535-85-9);Cobalt sulphate(10124-43-3)
	SEAT BELT PRETENTIONER	Lead(7439-92-1);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Cobalt(II) nitrate hexahydrate(10026-22-9)
	STEERING WHEEL GEAR SHIFT LEVER	N,N,N',N'-Tetramethyl-4,4'-methylenedianiline(101-61-1);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Diboron-trioxide(1303-86-2);Lead(7439-92-1);Lead-monoxide(1317-36-8);C,C'-azodi(formamide)(123-77-3);Cobalt-dinitrate(10141-05-6);Cobalt sulphate(10124-43-3)
	SWITCHES CONTROLLER	Lead-monoxide(1317-36-8);Lead(7439-92-1)
	THE OTHERS	Melamine(108-78-1);C,C'-azodi(formamide)(123-77-3);Lead-monoxide(1317-36-8);Lead(7439-92-1);Diboron-trioxide(1303-86-2);1,4-Dioxane(123-91-1);Cobalt-dinitrate(10141-05-6);N,N-Dimethylformamide(68-12-2);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Cobalt-sulfate-heptahydrate(10026-24-1);Boric acid(10043-35-3);Lead-titanium-trioxide(12060-00-3);TBBA(79-94-7);Octamethylcyclotetrasiloxane(556-67-2);Decamethylcyclopentasiloxane(541-02-6)
STEERING SUSPENSION	SUSPENSION	Melamine(108-78-1);Tris(nonylphenyl)phosphite(26523-78-4);4,4'-Isopropylidenediphenol(80-05-7)
	STEERING	Melamine(108-78-1);Boric acid(10043-35-3);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5)
BATTERY	BATTERY & MANAGEMENT SYSTEM	TBBA(79-94-7);Tris(2-chloroethyl) phosphate(115-96-8);Lead(7439-92-1);1-Methyl-2-pyrrolidone(872-50-4);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);C,C'-azodi(formamide)(123-77-3);Octamethylcyclotetrasiloxane(556-67-2)
	FUEL CELL & MANAGEMENT SYSTEM	
THE OTHERS	E-SCOOTER	
	CUSTOMIZING PART	

No specific safe use information is required – follow General Safe Use Information for Articles.