



Movement that inspires

SVHC List

[KIA MOTORS EUROPE] EV6 (CV)

Area	Parts	SVHCs present in component articles at greater than 0.1% w/w (CAS No)
BODY	STRUCTURE	C,C'-azodi(formamide)(123-77-3)
	BRAKE	Lead(7439-92-1);Cobalt(II) nitrate hexahydrate(10026-22-9);Di-(2-ethylhexyl)phthalat(117-81-7);2-Methylimidazole(693-98-1);Melamine(108-78-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);C,C'-azodi(formamide)(123-77-3);Octamethylcyclotetrasiloxane(556-67-2);Decamethylcyclopentasiloxane(541-02-6);Dodecamethylcyclohexasiloxane(540-97-6);Glycols, polyethylene, mono((1,1,3,3-tetramethylbutyl)phenyl) ether(9036-19-5)
	BUMPER	Melamine(108-78-1);C,C'-azodi(formamide)(123-77-3);Cobalt-dinitrate(10141-05-6);Di-(2-ethylhexyl)phthalat(117-81-7);Lead(7439-92-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Octamethylcyclotetrasiloxane(556-67-2);Decamethylcyclopentasiloxane(541-02-6);TBBA(79-94-7)
	GLASS GLASS MOULDING	Lead(7439-92-1)
	OUTSIDE LAMP OUTSIDE MIRROR	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Lead-monoxide(1317-36-8);Octamethylcyclotetrasiloxane(556-67-2);Lead(7439-92-1);Phenol, dimethyl-, phosphate (3:1)(25155-23-1);Di-(2-ethylhexyl)phthalat(117-81-7);C,C'-azodi(formamide)(123-77-3);Diboron-trioxide(1303-86-2);TBBA(79-94-7);Decamethylcyclopentasiloxane(541-02-6);1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione(2451-62-9)
	WHEEL TIRE	Lead titanium zirconium oxide(12626-81-2);Decamethylcyclopentasiloxane(541-02-6);Dodecamethylcyclohexasiloxane(540-97-6);1,2-Dimethoxyethane(110-71-4);1,3-Propanesultone(1120-71-4);Lead(7439-92-1)
	THE OTHERS	
DOOR SUNROOF	DOOR	Imidazolidine-2-thione(96-45-7);Lead(7439-92-1);C,C'-azodi(formamide)(123-77-3);Octamethylcyclotetrasiloxane(556-67-2);Decamethylcyclopentasiloxane(541-02-6);TBBA(79-94-7);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Tris(2-chloroethyl) phosphate(115-96-8);Di-(2-ethylhexyl)phthalat(117-81-7);6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol(119-47-1);Lead-titanium-trioxide(12060-00-3);Cobalt(II) nitrate hexahydrate(10026-22-9)
	HOOD	Di-(2-ethylhexyl)phthalat(117-81-7)
	SUNROOF	Lead(7439-92-1);C,C'-azodi(formamide)(123-77-3)

	TRUNK TAIL GATE	Imidazolidine-2-thione(96-45-7);Lead(7439-92-1);Lead-monoxide(1317-36-8);Lead-titanium-trioxide(12060-00-3);Diboron-trioxide(1303-86-2)
	THE OTHERS	Melamine(108-78-1);Cobalt-dinitrate(10141-05-6);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Lead(7439-92-1);Decamethylcyclopentasiloxane(541-02-6);;Octamethylcyclotetrasiloxane(556-67-2);Tris(nonylphenyl)phosphite(26523-78-4);C,C'-azodi(formamide)(123-77-3);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Lead(7439-92-1);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);1,4-Dioxane(123-91-1);N,N-Dimethylformamide(68-12-2);;Lead(7439-92-1);Boric acid(10043-35-3);Cobalt-dinitrate(10141-05-6);Cobalt-sulfate-heptahydrate(10026-24-1);Tris(2-chloroethyl) phosphate(115-96-8),C,C'-azodi(formamide)(123-77-3);Cobalt(II) nitrate hexahydrate(10026-22-9);Octamethylcyclotetrasiloxane(556-67-2);Decamethylcyclopentasiloxane(541-02-6);TBBA(79-94-7);C,C'-azodi(formamide)(123-77-3);Tris(2-methoxyethoxy)vinylsilane(1067-53-4);;N,N-Dimethylacetamide(127-19-5);2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol(25973-55-1)
ELECTRIC CONTROL	ELECTRIC CONTROL	Melamine(108-78-1);Lead(7439-92-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Decamethylcyclopentasiloxane(541-02-6);Dodecamethylcyclohexasiloxane(540-97-6);Lead titanium zirconium oxide(12626-81-2);;Di-(2-ethylhexyl)phthalat(117-81-7);Lead-titanium-trioxide(12060-00-3);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Octamethylcyclotetrasiloxane(556-67-2),TBBA(79-94-7);2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone(119313-12-1);Cobalt chloride(7791-13-1);Tris(2-chloroethyl) phosphate(115-96-8);Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide(75980-60-8)
	WIRING HARNESS	Melamine(108-78-1);Tris(2-chloroethyl) phosphate(115-96-8);Lead(7439-92-1);C,C'-azodi(formamide)(123-77-3);Octamethylcyclotetrasiloxane(556-67-2);Decamethylcyclopentasiloxane(541-02-6);Lead-monoxide(1317-36-8)
ENGINE ROOM	ENGINE TRANSMISSION	Melamine(108-78-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Lead(7439-92-1);Lead-titanium-trioxide(12060-00-3);Boric acid(10043-35-3);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);Octamethylcyclotetrasiloxane(556-67-2);Decamethylcyclopentasiloxane(541-02-6);1-Methyl-2-pyrrolidone(872-50-4);Tris(2-methoxyethoxy)vinylsilane(1067-53-4)
	HEATER & COOLING UNIT	C,C'-azodi(formamide)(123-77-3);Lead(7439-92-1);Diboron-trioxide(1303-86-2);Hexahydromethylphthalic-anhydride(25550-51-0);Lead-monoxide(1317-36-8);Tris(2-chloroethyl) phosphate(115-96-8);Octamethylcyclotetrasiloxane(556-67-2);8;Decamethylcyclopentasiloxane(541-02-6);4-Nonylphenol, branched(84852-15-3);Lead-titanium-trioxide(12060-00-3);Cobalt-dinitrate(10141-05-6),1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione(2451-62-9)
	THE OTHERS	Melamine(108-78-1);Cobalt-dinitrate(10141-05-6);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Lead(7439-92-1);Decamethylcyclopentasiloxane(541-02-6);;Octamethylcyclotetrasiloxane(556-67-2);Tris(nonylphenyl)phosphite(26523-78-4);C,C'-azodi(formamide)(123-77-3);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-

		5);Lead(7439-92-1);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);1,4-Dioxane(123-91-1);N,N-Dimethylformamide(68-12-2);;Lead(7439-92-1);Boric acid(10043-35-3);Cobalt-dinitrate(10141-05-6);Cobalt-sulfate-heptahydrate(10026-24-1);Tris(2-chloroethyl) phosphate(115-96-8),C,C'-azodi(formamide)(123-77-3);Cobalt(II) nitrate hexahydrate(10026-22-9);Octamethylcyclotetrasiloxane(556-67-2);Decamethylcyclopentasiloxane(541-02-6);TBBA(79-94-7);C,C'-azodi(formamide)(123-77-3);Tris(2-methoxyethoxy)vinylsilane(1067-53-4);;N,N-Dimethylacetamide(127-19-5);2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol(25973-55-1)
INTERIOR	AIR BAG	
	CONSOLE	Lead(7439-92-1);Lead-monoxide(1317-36-8);TBBA(79-94-7);Tris(2-chloroethyl) phosphate(115-96-8);Boric acid(10043-35-3);Octamethylcyclotetrasiloxane(556-67-2);Decamethylcyclopentasiloxane(541-02-6); Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide(75980-60-8)
	CRASH PAD	C,C'-azodi(formamide)(123-77-3);Tris(2-chloroethyl) phosphate(115-96-8);TBBA(79-94-7);1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione(2451-62-9);Cyclohexane-1,2-dicarboxylic anhydride(85-42-7);Lead(7439-92-1);Lead-monoxide(1317-36-8);2-Ethoxyethyl acetate(111-15-9)
	DISPLAY	Lead(7439-92-1);Diboron-trioxide(1303-86-2);Lead-monoxide(1317-36-8);Lead titanium zirconium oxide(12626-81-2);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione(2451-62-9);Tris(2-chloroethyl) phosphate(115-96-8);Lead-titanium-trioxide(12060-00-3)
	HEADLINING	TBBA(79-94-7);C,C'-azodi(formamide)(123-77-3);Lead(7439-92-1);Diboron-trioxide(1303-86-2);2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone(119313-12-1)
	SEAT ARM REST	Tris(2-chloroethyl) phosphate(115-96-8);Lead(7439-92-1);Melamine(108-78-1);TBBA(79-94-7);2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one(71868-10-5);C,C'-azodi(formamide)(123-77-3);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Cobalt-sulfate-heptahydrate(10026-24-1)
	SEAT BELT PRETENTIONER	Cobalt-dinitrate(10141-05-6);Cobalt(II) nitrate hexahydrate(10026-22-9);1-Methyl-2-pyrrolidone(872-50-4)
	STEERING WHEEL GEAR SHIFT LEVER	Tris(2-chloroethyl) phosphate(115-96-8);TBBA(79-94-7);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Lead(7439-92-1);Cobalt sulphate(10124-43-3)
	SWITCHES CONTROLLER	Lead-monoxide(1317-36-8);Lead(7439-92-1)
	THE OTHERS	
STEERING SUSPENSION	SUSPENSION	Lead(7439-92-1);Melamine(108-78-1);4,4'-Isopropylidenediphenol(80-05-7)
	STEERING	Lead(7439-92-1);Lead-monoxide(1317-36-8);Diboron-trioxide(1303-86-2);Octamethylcyclotetrasiloxane(556-67-2)
BATTERY	BATTERY & MANAGEMENT SYSTEM	Melamine(108-78-1);Cobalt sulphate(10124-43-3);Tris(2-chloroethyl) phosphate(115-96-8);Lead-monoxide(1317-36-8);Lead(7439-92-1);Diboron-trioxide(1303-86-2);Cobalt-dinitrate(10141-05-6);Tris(2-methoxyethoxy)vinylsilane(1067-53-4);Cobalt chloride(7791-13-1);1-Methyl-2-pyrrolidone(872-50-4);Tris(nonylphenyl)phosphite(26523-78-4);Octamethylcyclotetrasiloxane(556-67-2);Decamethylcyclopentasiloxane(541-02-6);Lead-titanium-trioxide(12060-00-3)

	FUEL CELL & MANAGEMENT SYSTEM	
THE OTHERS	E-SCOOTER	
	CUSTOMIZING PART	Lead(7439-92-1);Lead-monoxide(1317-36-8)

No specific safe use information is required – follow General Safe Use Information for Articles.